

Jura Impressa X7

Strip & Clean

It is recommended that this clean is carried out at least once per week

It should also be carried out to solve the following problems

- Milk not foaming properly
- Cold drinks
- Not sucking milk (if this problem isn't fixed by cleaning then carry out a descale)

Instructions

- Carefully remove cap 01 by pushing release button 12
- Remove pieces 02 – 08 (marked in red) and soak in strong solution of cappuccino cleaner (50:50) for around 30 mins
- Ensure valve 05 is clear. If blocked it can be cleared by pushing a small pin or paper clip down either end. Do not use anything larger than the hole or the part will be damaged.
- Rinse all parts thoroughly in clean water
- Re-assemble as per diagram

<u>KEY</u>	
1	Cap silver
2	Outlet
3	Foam nozzle autocappuccino set
4	Discharge channel
5	Cover cap black
6	Adapter 1.5mm
7	O-ring
8	Silicone hose
9	Milk hose
10	Steam hose
11	Outlet gate support
12	Release button

